

Release Notes 9.7.4

English

Fixed a bug which made it impossible to carry out the surgery as originally intended when the surgical protocol was used in combination with specific implants. The following implants are affected:

Straumann Bone Level Tapered Roxolid SLActive:

- 021.0010 (L: 10mm; Ø 2.9mm; SC)
- 021.0012 (L: 12mm; Ø 2.9mm; SC)
- 021.0014 (L: 14mm; Ø 2.9mm; SC)

Deutsch

Behebung eines Problems, dass es bei Verwendung des chirurgischen Protokolls in Verbindung mit bestimmten Implantaten unmöglich machte, den Eingriff in der ursprünglich vorgesehenen Art und Weise durchzuführen. Betroffen sind die folgenden Implantate:

Straumann Bone Level Tapered Roxolid SLActive:

- 021.0010 (L: 10mm; Ø 2.9mm; SC)
- 021.0012 (L: 12mm; Ø 2.9mm; SC)
- 021.0014 (L: 14mm; Ø 2.9mm; SC)