

Release Notes 9.6.4

English

- Planning layout added to show tangential view and 3D view only (#4523).
- Improved support of surgical procedure for Straumann Bone Level Tapered Implant (#4569).
- In digital drill guide wizard, a problem was fixed with displaying sleeves while editing bone support (#4575).
- Infrequent problem with printing on Windows 10 fixed (#4564).
- Several minor bugs fixed.

Deutsch

- Neues Planungslayout hinzugefügt, welches nur Tangential- und 3D-View anzeigt (#4523).
- Verbesserte Unterstützung des chirurgischen Verfahrens für Straumann Bone Level Tapered Implantate (#4569).
- Im Bohrschablonenassistenten wurde ein Problem mit der Anzeige von Bohrhülsen beim Bearbeiten der Knochenauflage behoben (#4575).
- Ein seltenes Problem beim Drucken unter Windows 10 wurde behoben (#4564).
- Weitere kleinere Fehler beseitigt.