

# Release Notes 10.4.2

We're constantly working to improve your experience with coDiagnostiX. Below you will find a summary of the items fixed or improved upon in this update.

## REGIONAL DISABLING OF SLEEVE SYSTEMS

Some sleeve systems, that are not yet available in all geographical regions are now disabled for users in these regions. This currently affects the following systems in North America:

- Anthogyr Pin sleeve 2.0
- bredent medical pro guide fixation pin sleeve
- Medentika MedentiGuide
- Straumann Korea Guided Surgery
- YDM Clamp Guided

## BUGFIXES

The following issues have been fixed with the coDiagnostiX 10.4.2 release:

**Implant rotation:** Fixed a bug that affected the implant rotation markers on surgical guides when using implants with an odd number of edges in the implant platform interface (see image).

**Surgical guide display:** Fixed a display bug affecting surgical guides, which made them disappear when closing and reopening the wizard during guide editing.

